


T. 143 R. 27 M. 5TH Coordinates: X _____ Y _____
NE 23 Corner common to sections 13, 14, 23, 24



EXISTING SURVEYS

Original Government Survey

Year surveyed 1873
Original monument lost

Original Evidence Found

Year of search _____ By _____
Monument found _____

Bearing Trees

| Species | Tam | Cedar | Cedar | Tam |
|----------|-------|-------|-------|-------|
| Diameter | 8" | 6" | 7" | 8" |
| Bearing | N33E | N22W | S56W | S3E |
| Distance | 10LKS | 13LKS | 11LKS | 19LKS |

Original Bearing Trees Found

| Species | _____ | _____ | _____ | _____ |
|----------|-------|-------|-------|-------|
| Diameter | _____ | _____ | _____ | _____ |
| Bearing | _____ | _____ | _____ | _____ |
| Distance | _____ | _____ | _____ | _____ |

O = Corner

Subsequent Corner Restoration

Year surveyed ? By Geo. Ralph
Location filed COUNTY SURVEY RECORD BOOK B" P.97
Monument END OLD POST - OLD BITS: 12" TAM S - 11.9', 6" CEDAR S 63-30 W 7'

also on microfilm - roll 1115 BK 82 P 40

Bearing Trees, Reference Objects

| Species | CEDAR | END OF CULVERT | END OF CULVERT |
|----------|---------|----------------|----------------|
| Diameter | 8" | SCREW | SCREW |
| Bearing | N41-30W | S45E | N46E |
| Distance | 44.6' | 25.4' | 27.9' |

Evidence of Subsequent Corner Restoration

Year of search 1925 By Co Hwy Dept
State RP # 4 BOOK 154 PAGE 23
corner

Bearing Trees, Reference Objects

| Screw end of CMC | Screw end of CMC | Tam |
|------------------|------------------|--------------|
| <u>S49°E</u> | <u>N46°E</u> | <u>N20°E</u> |
| <u>25.4'</u> | <u>27.9'</u> | <u>50.2'</u> |

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search 1999 By L. Levelling RLS 16089
Set, 6" x 24" galv. steel pipe w/ brass cap
buried in E Co. Rd. 135 and 10.50' west of
E of existing culv. Position perpetuates
the orig. GEO + Cass Co. survey personnel
position.

- REF. TIES:

| | | |
|-----------------------|----------------|-------------------------|
| <u>6" Ash</u> | <u>N 60° E</u> | <u>116.27'</u> |
| <u>Steel Signpost</u> | <u>S 57° E</u> | <u>50.51'</u> |
| <u>" " "</u> | <u>S 21° W</u> | <u>17.63' (FS 54-9)</u> |
| <u>" " "</u> | <u>N 20° W</u> | <u>37.19'</u> |

CERT. OF LOCATION 5/17/99
DOC. # 412847