


T. 143 R. 27 M. 5TH Coordinates: X _____ Y _____
NE 28 Corner common to sections 21, 22, 27, 28



EXISTING SURVEYS

Original Government Survey

Year surveyed 1873

Original monument Post

Bearing Trees	
Species <u>Spruce</u>	<u>Spruce</u>
Diameter <u>6"</u>	<u>10"</u>
Bearing <u>N6W</u>	<u>N66E</u>
Distance <u>2545</u>	<u>3445</u>

Original Evidence Found

Year of search _____ By _____

Monument found _____

Original Bearing Trees Found

Species _____	_____
Diameter _____	_____
Bearing _____	_____
Distance _____	_____

Subsequent Corner Restoration

Year surveyed _____ By _____

Location filed _____

Monument _____

Evidence of Subsequent Corner Restoration

Year of search 1998 By NLSEM RLS #16089

Set a 2" x 24" galv. steel pipe w/ brass cap, on E, below surface.

Steel Sign Post, N3°E, 10.83'

Bearing Trees, Reference Objects

Species _____	_____
Diameter _____	_____
Bearing _____	_____
Distance _____	_____

Bearing Trees, Reference Objects

<u>Ash</u>	<u>Ash</u>	<u>Aspen</u>	<u>Aspen</u>
<u>7"</u>	<u>5"</u>	<u>8"</u>	<u>5"</u>
<u>S26W</u>	<u>N33°E</u>	<u>S72°E</u>	<u>N52°W</u>
<u>13.27'</u>	<u>51.25'</u>	<u>34.64'</u>	<u>30.29'</u>

Subsequent Corner Restoration

Year surveyed _____ By _____

Location filed _____

Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____