

Index No. _____

CASS COUNTY LAND CORNER RECORD

T. _____ R. _____ M. _____ Coordinates: X _____ Y _____

Corner common to sections _____



= Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed _____
Original monument _____

Original Evidence Found

Year of search _____ by _____
Monument found _____

Bearing Trees

Species _____
Diameter _____
Bearing _____
Distance _____

Original Bearing Trees Found

Species _____
Diameter _____
Bearing _____
Distance _____

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed:
Monument:

Evidence of Subsequent Corner Restoration

Year of search _____ By _____
Location filed:
Monument:

Bearing Trees, Reference Objects

Species _____
Diameter _____
Bearing _____
Distance _____

Bearing Trees, Reference Objects

Species _____
Diameter _____
Bearing _____
Distance _____

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed:
Monument:


Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
Location filed:
Monument:

Index No. R5

CASS COUNTY LAND CORNER RECORD

T. 143 R. 27 M. 5TH Coordinates: X _____ Y _____
NE 30 Corner common to sections 19, 20, 29, 30



EXISTING SURVEYS

Original Government Survey

Year surveyed 1873
Original monument Post

Original Evidence Found

Year of search _____ By _____
Monument found _____

Species	Bearing	Tree	Distance
<u>Aspen</u>	<u>Aspen</u>	<u>White</u>	<u>Aspen</u>
<u>14"</u>	<u>6"</u>	<u>8"</u>	<u>16"</u>
<u>N58E</u>	<u>S22E</u>	<u>S53W</u>	<u>N57W</u>
<u>19LKS</u>	<u>38LKS</u>	<u>23LKS</u>	<u>26LKS</u>

Species	Bearing	Tree	Distance
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

Subsequent Corner Restoration

Year surveyed 1920 By E. B. Horst
Location filed COUNTY RESURVEY "E-7"
Monument IRON MONUMENT
1920, BEN CLARK Bldg "C" P. 392 Fwd Hub, P. 394
SET IRON POST 3" X 24"

Evidence of Subsequent Corner Restoration

Year of search 1967 By Co. Hwt Dept.
Co. Rd # 63
Found 2" I.P.

Bearing Trees, Reference Objects

Species	Bearing	Tree	Distance
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

Bearing Trees, Reference Objects

Species	Bearing	Tree	Distance
<u>Power Guy pole</u>	<u>8"</u>	<u>Poplar</u>	<u>8"</u>
<u>NW</u>	<u>South</u>	<u>SE</u>	
<u>48.6'</u>	<u>27.0'</u>	<u>44.5'</u>	

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
1986 Certificate - Walter Curo
Doc. # 291485
Found brass cap monument in concrete
down 8" in old road bed with 2 1/2"
capped iron pipe 0.33' North
10" W. Oak N80W 102.03';
5" W. Oak S5W 19.83';
6" Twin W. Oak S50 E 53.50';
8" Elm N21E 66.91'

Remonumentation certificate prepared _____
Filed at _____

By _____
Date _____