Index No. I-13

CASS COUNTY LAND CORNER RECORD

T. 143 R. 27 M. 5th Coordinates: X _____ Y _____

E 1/4 Corner common to sections 27, 28



EXISTING SURVEYS

Original Government Survey

Year surveyed 1873

Original monument Post

Bearing Trees

Species	Aspen	Cedar		
Diameter	6"	7"		
Bearing	S47°W	N3°E		
Distance	12 lks	9 lks		

Original Evidence Found

Year of search _____ By _____

Monument found _____

Original Bearing Trees Found

Species				
Diameter				
Bearing				
Distance				

Subsequent Corner Restoration

Year surveyed 1998 By NLSEM RLS #16089

Location filed USFS Cass Lake & CCSO

Monument 2" x 24" galv. steel pipe w/ brass Cap. 6.5' north of E-W fence line.

Bearing Trees, Reference Objects

Species	Aspen	Oak	Aspen	Steel Sign Post
Diameter	7"	7"	7"	
Bearing	S86°E	S61°E	S32°W	S26°W
Distance	32.94'	62.50'	43.56'	12.28'

Evidence of Subsequent Corner Restoration

Year of search _____ By _____

Bearing Trees, Reference Objects

Subsequent Corner Restoration

Year surveyed _____ By _____

Location filed

Monument

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____

Remonumentation certificate prepared _____ By NLSEM

Filed at CCRO Doc. #412857 (414547 correct) Date 7/2/99