


Index No. T 17

CASS COUNTY LAND CORNER RECORD

T. 143 R. 27 M. 514 Coordinates: X _____ Y _____
E 1/4 27 Corner common to sections 26 & 27



○ = Corner

EXISTING SURVEYS

Original Government Survey
Year surveyed 1873
Original monument Post

Original Evidence Found
Year of search _____ By _____
Monument found _____

Bearing Trees
Species Spruce Pine Birch
Diameter 7" 12"
Bearing N52W N40E
Distance 6 LKS 9 LKS

Original Bearing Trees Found
Species _____
Diameter _____
Bearing _____
Distance _____

Subsequent Corner Restoration
Year surveyed 1998 By NLSEM PLS #16089
Location filed USFS Cass Lake & CCSO
Monument Set a 2"x48" galv. steel pipe w/brass cap, 11" above ground.

Evidence of Subsequent Corner Restoration
Year of search _____ By _____

Bearing Trees, Reference Objects
Species Ash Ash B. of G. Steel
Diameter 8" 6" 11" Sign Post
Bearing S34°E N59°E N33°W N29°E
Distance 23.46' 19.40' 12.19 2.47'

Bearing Trees, Reference Objects

Subsequent Corner Restoration
Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration Found
Year of search _____ By _____

Re monumentation certificate prepared
Filed at CCRO Dec. # 412850

By NLSEM
Date 5/17/99