


T. 143 R. 27 M. 5TH Coordinates: X _____ Y _____
E1429 Corner common to sections 28,29



○ = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1873
Original monument POST

Original Evidence Found

Year of search _____ By _____
Monument found _____

Species	<u>Aspen</u>	<u>Birch</u>	_____	_____
Diameter	<u>4"</u>	<u>7"</u>	_____	_____
Bearing	<u>N15W</u>	<u>S38E</u>	_____	_____
Distance	<u>10 LKS</u>	<u>22 LKS</u>	_____	_____

Original Bearing Trees Found

Species	_____	_____	_____	_____
Diameter	_____	_____	_____	_____
Bearing	_____	_____	_____	_____
Distance	_____	_____	_____	_____

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration

Year of search 1998 By NLSEM RLS #16089
Set a 2"x48" Adv. steel pipe w/ brass cap, 10" above ground.

Bearing Trees, Reference Objects

Species	_____	_____	_____	_____
Diameter	_____	_____	_____	_____
Bearing	_____	_____	_____	_____
Distance	_____	_____	_____	_____

Bearing Trees, Reference Objects

<u>Ash</u>	<u>Steel</u>	<u>Steel</u>	<u>Steel</u>
<u>5"</u>	<u>Sign Post</u>	<u>Sign Post</u>	<u>Sign Post</u>
<u>N15°E</u>	<u>S88°E</u>	<u>S45°E</u>	<u>N60°E</u>
<u>29.47'</u>	<u>7.18'</u>	<u>14.60'</u>	<u>14.77'</u>

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____