T. 143 R. 27 M. 574 Coordinates: X E14 36 Corner common to sections 36 AND 3	
Original Government Survey	SURVEYS Original Evidence Found
Year surveyed 1672	
	Year of searchBy
Original monument lost	Monument found
Species Birch Soft maple	Original Bearing Trees Found O = Corner Species
Diameter 8" 6"	Diameter
Bearing 537W N52W	Bearing
Distance 4LKS 20LKS	Distance
Subsequent Corner Restoration	Evidence of Subsequent Corner Restoration
Year surveyed 1986 By KEn Whitehorn	Year of searchBy
Location filed	•
Monument Set 21/2"x 60" galvanized inon	
pipe with magnet at have and 3"	
stamped brass tablet.	
The state of the s	
Bearing Trees, Reference Objects	Position Trans. Policies Objects
Species W. Oak W. Oak W. Oak	Bearing Trees, Reference Objects
Diameter 51/2" 9" 8"	
Diameter <u> </u>	
Bearing <u>N3W</u> <u>567W</u> <u>576F</u>	II
MA CAN A ACMAI BA AMA	
Distance 50.97' 29.50' 42.08'	
Distance 50.97" 29.50" 42.08" Subsequent Corner Restoration	Evidence of Subsequent Corner Restoration Found
	Evidence of Subsequent Corner Restoration Found Year of search By 1980 Certificate - Ken Whitehorn Doc. # 289690
Subsequent Corner Restoration Tear surveyed By Location filed	Year of search ByBy
Subsequent Corner Restoration Tear surveyed By Location filed	Year of search ByBy
Subsequent Corner Restoration Tear surveyed By Location filed	Year of search ByBy
Subsequent Corner Restoration Tear surveyed By Location filed	Year of search ByBy
Subsequent Corner Restoration Tear surveyed By Location filed	Year of search ByBy
Subsequent Corner Restoration Tear surveyed By Location filed	Year of search ByBy
Subsequent Corner Restoration Tear surveyed By Location filed	Year of search ByBy
Subsequent Corner Restoration Tear surveyed By Ocation filed	Year of search ByBy
Subsequent Corner Restoration Tear surveyed By Ocation filed	Year of search ByBy
Subsequent Corner Restoration Tear surveyed By Location filed	Year of search ByBy
Subsequent Corner Restoration Tear surveyed By Ocation filed	Year of search ByBy
Subsequent Corner Restoration Tear surveyed By Location filed	Year of search ByBy
Subsequent Corner Restoration ear surveyed By ocation filed	Year of search ByBy