


Index No. A 19

CASS COUNTY LAND CORNER RECORD

T. 143 R. 28 M. 5TH Coordinates: X _____ Y _____
N¹⁴ 2 Corner common to sections 2 AND 35-144-28



○ = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1873
Original monument Post

Original Evidence Found

Year of search _____ By _____
Monument found _____

Bearing Trees

Species	<u>Tam</u>	<u>Tam</u>	_____
Diameter	<u>3"</u>	<u>12"</u>	_____
Bearing	<u>N61W</u>	<u>East</u>	_____
Distance	<u>5 LKS</u>	<u>15 LKS</u>	_____

Original Bearing Trees Found

Species	_____	_____	_____
Diameter	_____	_____	_____
Bearing	_____	_____	_____
Distance	_____	_____	_____

Subsequent Corner Restoration

Year surveyed 1912 By HARRY S. TODD.
Location filed COUNTY SURVEY RECORD BOOK "A" P. 532-535
Monument FIND OLD GROUT BITS: 3" TAM N61W 5 LKS, 12" TAM EAST 15 LKS. SET 2 1/2 X 48" GALV. I.P. WITH 3" CAP.

Evidence of Subsequent Corner Restoration

Year of search 1925 By Co. Hwy Dept.
State Road #4
Found 3" galv. I.P.

1915, E.B. HIRST COUNTY BOOK "C" P. 272 FIND 2 1/2 X 48" I.P.
- also on microfilm - roll 115 BK 71 P. 4

1912 - also on microfilm - roll 115 BK 74 P. 59-60

Bearing Trees, Reference Objects

Species	<u>TAM</u>	<u>TAM.</u>	_____
Diameter	<u>15"</u>	<u>14"</u>	_____
Bearing	<u>N33-46W</u>	<u>N44-18 E</u>	_____
Distance	<u>42.73'</u>	<u>46.30'</u>	_____

CROSS 1913 TIES: "A" P 559-563

Bearing Trees, Reference Objects

<u>Tam stump</u>	<u>Tam stump</u>	_____
<u>14"</u>	<u>8"</u>	_____
<u>NE</u>	<u>N</u>	_____
<u>77.5'</u>	<u>37.2'</u>	_____

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____

Remonumentation certificate prepared _____ By _____

Filed at _____ Date _____