Index No. A-21 CASS COUNTY LAND CORNER RECORD	
143 B 28 M Soft Conditions V	
T. <u>143</u> R. <u>28</u> M. <u>5rH</u> Coordinates: X NE Z Corner common to sections <u>1,2 Aug</u> 35	7.36-144-28
	3 SURVEYS
Original Government Survey	Original Evidence Found
Year surveyed Not Set In	Year of search By
Original monument original in lake	Monument found
Bearing Trees Species	Original Bearing Trees Found O = Corner Species
Diameter	Diameter
Bearing	Bearing
Distance	Distance
Subsequent Corner Restoration	Evidence of Subsequent Corner Restoration
Year surveyed 1913 By John Curo	Year of searchBy
Location filed COUNTY SURVEY RECORD BOOK A" P.559-563	
Monument Set 21/2 x 48" GALUI I.P. W/3" (AP	
PROPORTIONALLY	
Bearing Trees, Reference Objects Species	Bearing Trees, Reference Objects
•	
Diameter	
· · · · · ·	
Distance	
Subsequent Corner Restoration Year surveyed By Location filed Monument	
· · · · · · · · · · · · · · · · · · ·	
Remonumentation certificate prepared	
Filed at	Date