


Index No. A 9

CASS COUNTY LAND CORNER RECORD



T. 143 R. 28 M. 5TH Coordinates: X \_\_\_\_\_ Y \_\_\_\_\_  
NE 5 Corner common to sections 4, 5 AND 32, 33 - 144-28

EXISTING SURVEYS

Original Government Survey

Year surveyed 1873  
Original monument Post

Original Evidence Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
Monument found \_\_\_\_\_

	Bearing	Trees	
Species	<u>Tam</u>	<u>Tam</u>	<u>Tam</u>
Diameter	<u>3"</u>	<u>4"</u>	<u>3"</u>
Bearing	<u>S22E</u>	<u>N7W</u>	<u>N64E</u>
Distance	<u>1745</u>	<u>28LKS</u>	<u>38LKS</u>

Original Bearing Trees Found

Species	_____	_____	_____
Diameter	_____	_____	_____
Bearing	_____	_____	_____
Distance	_____	_____	_____

Subsequent Corner Restoration

Year surveyed 1914 By John Curo  
Location filed COUNTY SURVEY RECORD BOOK "B" P.40-45  
Monument Find 2" SQUARE SPRUCE TREE FOR CORNER  
1916, E.P. HORSBY BOOK "C" P. 356 Find STUMP OF SPRUCE TREE COR.  
AND Curo's B.T'S.

Evidence of Subsequent Corner Restoration

Year of search 1916 By A. Nowak  
microfilm - roll 105 BK 54B V. 93  
Find corner and Curo's 1914 B.T'S

Bearing Trees, Reference Objects OLD SE B.T.

Species	<u>DEAD TAM.</u>	<u>DEAD TAM.</u>	<u>DEAD TAM.</u>	<u>DEAD TAM.</u>
Diameter	<u>5"</u>	<u>4"</u>	<u>3"</u>	<u>2"</u>
Bearing	<u>S54E</u>	<u>S23W</u>	<u>N11-40E</u>	<u>S51E</u>
Distance	<u>170'</u>	<u>85.35'</u>	<u>57.40'</u>	<u>9.15'</u>

Bearing Trees, Reference Objects

_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

1914 TIES.

Subsequent Corner Restoration

Year surveyed \_\_\_\_\_ By \_\_\_\_\_  
Location filed \_\_\_\_\_  
Monument \_\_\_\_\_

Evidence of Subsequent Corner Restoration Found

Year of search \_\_\_\_\_ By \_\_\_\_\_

Remonumentation certificate prepared \_\_\_\_\_ By \_\_\_\_\_

Filed at \_\_\_\_\_ Date \_\_\_\_\_