Index No. E 13

CASS COUNTY LAND CORNER RECORD

T. 143 R. 28 M. 5TH Coordinates: X _____ Y _____

NE 9 Corner common to sections 3, 4, 9, 10



O = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1873

Original monument Post

Bearing Trees

Species	Fir	Balm Gilead	Aspen	Elm
Diameter	10"	12"	16"	6"
Bearing	S76W	S7E	N50E	N39W
Distance	20 LKS	16 LKS	36 LKS	20 LKS

Original Evidence Found

Year of search _____ By _____

Monument found _____

Original Bearing Trees Found

Species				
Diameter				
Bearing				
Distance				

Subsequent Corner Restoration

Year surveyed 1916 By E.B. Horst

Location filed County Book C" P. 553

Monument ESTABLISH CORNER FROM B.T.S: 6" ELM N 39W 20, SNAG OF BALM GILEAD S7E 16 also on microfilm - roll 105 BK 54B P 33

Evidence of Subsequent Corner Restoration

Year of search _____ By _____

Bearing Trees, Reference Objects

Species				
Diameter				
Bearing				
Distance				

Bearing Trees, Reference Objects

Subsequent Corner Restoration

Year surveyed _____ By _____

Location filed _____

Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____

Remonumentation certificate prepared _____ By _____

Filed at _____ Date _____