


Index No. E 21

CASS COUNTY LAND CORNER RECORD

T. 143 R. 28 M. 5TH Coordinates: X _____ Y _____
NE 11 Corner common to sections 11, 12, 12



○ = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1873
Original monument Post

Original Evidence Found

Year of search _____ By _____
Monument found _____

Bearing Trees

Species	<u>Tam</u>	<u>Tam</u>	<u>Tam</u>	<u>Tam</u>
Diameter	<u>8"</u>	<u>8"</u>	<u>8"</u>	<u>14"</u>
Bearing	<u>N60E</u>	<u>N80W</u>	<u>S22E</u>	<u>S39W</u>
Distance	<u>22 LKS</u>	<u>11 LKS</u>	<u>23 LKS</u>	<u>23 LKS</u>

Original Bearing Trees Found

Species	_____	_____	_____	_____
Diameter	_____	_____	_____	_____
Bearing	_____	_____	_____	_____
Distance	_____	_____	_____	_____

Subsequent Corner Restoration

Year surveyed 8 By Geo RALPH
Location filed COUNTY SURVEY RECORD BOOK 'B' P. 94-95
Monument FWO OLD POST

Evidence of Subsequent Corner Restoration

Year of search 1925 By Co. Hwy. Dept.
State Rd # 4
Found corner

also on microfilm - roll 115 BK 82 P. 31

Bearing Trees, Reference Objects

Species	<u>ASH</u>	<u>SPRUCE</u>	<u>CEDAR</u>
Diameter	<u>8"</u>	<u>9"</u>	<u>12"</u>
Bearing	<u>S21-30W</u>	<u>S65E</u>	<u>N64E</u>
Distance	<u>74'</u>	<u>69.5'</u>	<u>56.0'</u>

Bearing Trees, Reference Objects

Species	<u>Birch</u>	<u>ASH</u>	_____
Diameter	<u>10"</u>	<u>4"</u>	_____
Bearing	<u>SE</u>	<u>NE</u>	_____
Distance	<u>62.0'</u>	<u>53.0'</u>	_____

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____

Remonumentation certificate prepared _____ By _____
Filed at _____ Date _____