


Index No. E 23

CASS COUNTY LAND CORNER RECORD

T. 143 R. 28 M. 5TH Coordinates: X \_\_\_\_\_ Y \_\_\_\_\_  
N1/4 12 Corner common to sections 1112



○ = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1873  
Original monument Post

Original Evidence Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
Monument found \_\_\_\_\_

	Bearing Trees	
Species	<u>Spruce</u>	<u>Ash</u>
Diameter	<u>10"</u>	<u>5"</u>
Bearing	<u>N29E</u>	<u>S29E</u>
Distance	<u>19LKS</u>	<u>12LKS</u>

Original Bearing Trees Found	
Species	_____
Diameter	_____
Bearing	_____
Distance	_____

Subsequent Corner Restoration

Year surveyed ? By GEO RALPH  
Location filed COUNTY SURVEY RECORD BOOK 'B' P.94-95  
Monument FIND OLD CORNER POST - OLD B.T! SPRUCE  
NE 16' (DOWN)

Evidence of Subsequent Corner Restoration

Year of search 1925 By Co. Hwy Dept.  
State Road #4  
Corner

also on microfilm - roll 115 BK 82 P.31

Bearing Trees, Reference Objects

Species	<u>ASH</u>	<u>BIRCH</u>
Diameter	<u>16"</u>	<u>12"</u>
Bearing	<u>S72W</u>	<u>N74W</u>
Distance	<u>96.3'</u>	<u>126.2'</u>

Bearing Trees, Reference Objects

<u>Aspen</u>	<u>Aspen</u>
<u>9"</u>	<u>6"</u>
<u>SW</u>	<u>S</u>
<u>42.0'</u>	<u>36.0'</u>

Subsequent Corner Restoration

Year surveyed \_\_\_\_\_ By \_\_\_\_\_  
Location filed \_\_\_\_\_  
Monument \_\_\_\_\_

Evidence of Subsequent Corner Restoration Found

Year of search \_\_\_\_\_ By \_\_\_\_\_

Remonumentation certificate prepared \_\_\_\_\_ By \_\_\_\_\_  
Filed at \_\_\_\_\_ Date \_\_\_\_\_