


Index No. E 25

CASS COUNTY LAND CORNER RECORD



T. 143 R. 28 M. 5TH Coordinates: X _____ Y _____
NE 12 Corner common to sections 112 AND 617 - 143-27

EXISTING SURVEYS

Original Government Survey

Year surveyed 1873
Original monument Post

Original Evidence Found

Year of search _____ By _____
Monument found _____

Species	Bearing Trees			
	Birch	Paplar	Paplar	Paplar
Diameter	<u>20"</u>	<u>8"</u>	<u>6"</u>	<u>10"</u>
Bearing	<u>N60W</u>	<u>N60E</u>	<u>S53W</u>	<u>South</u>
Distance	<u>11LKS</u>	<u>21LKS</u>	<u>57LKS</u>	<u>100LKS</u>

Original Bearing Trees Found

Species	Diameter	Bearing	Distance
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

Subsequent Corner Restoration

Year surveyed ? By GEO RALPH
Location filed COUNTY SURVEY RECORD BOOK B P. 94-95
Monument OLD POST BEEN RE-ESTABLISHED

Evidence of Subsequent Corner Restoration

Year of search 1925 By Co. Hwy Dept
State Road #4
Found corner

also on microfilm - roll 115 BK 82 P. 31

Bearing Trees, Reference Objects

Species	Birch	Birch	
Diameter	<u>15"</u>	<u>12"</u>	_____
Bearing	<u>SW</u>	<u>NW</u>	_____
Distance	<u>59.4'</u>	<u>49'</u>	_____

Bearing Trees, Reference Objects

Birch	Birch	Basswood
<u>15"</u>	<u>12"</u>	<u>15"</u>
<u>SW</u>	<u>NW</u>	<u>NE</u>
<u>59.4'</u>	<u>49.0'</u>	<u>53.0'</u>

Subsequent Corner Restoration

Year surveyed 7/02 By CCSO
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____

Found God spike, down 0.3', on E & E
8" w. Oak N5°E 32.53' dbl hd nail
10" w. Oak N65°E 57.36' dbl hd nail
8" Maple S25°E 64.45' dbl hd nail
4" Birch S35°W 50.84' dbl hd nail

Remonumentation certificate prepared _____

By _____

Filed at _____

Date _____