


Index No. G 21

CASS COUNTY LAND CORNER RECORD

T. 143 R. 30 M. 5TH Coordinates: X \_\_\_\_\_ Y \_\_\_\_\_  
E 1/4 11 Corner common to sections 11, 12



○ = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1875  
Original monument Post

Original Evidence Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
Monument found \_\_\_\_\_

Bearing Trees

Species Tam Tam \_\_\_\_\_  
Diameter 4" 4" \_\_\_\_\_  
Bearing S 80 E S 41 W \_\_\_\_\_  
Distance 87 LKS 97 LKS \_\_\_\_\_

Original Bearing Trees Found

Species \_\_\_\_\_  
Diameter \_\_\_\_\_  
Bearing \_\_\_\_\_  
Distance \_\_\_\_\_

Subsequent Corner Restoration

Year surveyed 1924 By GLD  
Location filed Sec. of State  
Monument no orig. evidence set 1x3/4" w/ brass cap  
1/4"  
5 1/2" x 1/2"  
1924

Evidence of Subsequent Corner Restoration

Year of search 1983 By Walt Curo  
Corner Certificate  
Find brass cap monument broken off - nailed  
oak post on N. Side set 3/4" x 5' aluminum  
post w/ 3" aluminum cap

Bearing Trees, Reference Objects

Species Set oak post 8' long 6" SQUARE N. 1/4' alongside  
Diameter \_\_\_\_\_  
Bearing \_\_\_\_\_  
Distance \_\_\_\_\_  
iron post

Bearing Trees, Reference Objects

steel sign  
posts 3" 8' by  
3.5' East  
3.4' South

Subsequent Corner Restoration

Year surveyed \_\_\_\_\_ By \_\_\_\_\_  
Location filed \_\_\_\_\_  
Monument \_\_\_\_\_

Evidence of Subsequent Corner Restoration Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
Certificate - Walt Curo - filed by USFS 1984  
Doc # 279160 dated 1983

Remonumentation certificate prepared \_\_\_\_\_ By \_\_\_\_\_  
Filed at \_\_\_\_\_ Date \_\_\_\_\_