


T. 143 R. 30 M. 5TH Coordinates: X _____ Y _____
MC# 8 Corner common to sections 11, 14



EXISTING SURVEYS

Original Government Survey

Year surveyed 1875
Original monument Post

Original Evidence Found

Year of search _____ By _____
Monument found _____

Bearing Trees

Species	<u>Sugar</u>	<u>Elm</u>	_____
Diameter	<u>12"</u>	<u>6"</u>	_____
Bearing	<u>S75W</u>	<u>N1W</u>	_____
Distance	<u>244s</u>	<u>9Lks</u>	_____

Original Bearing Trees Found

Species	_____	_____	_____
Diameter	_____	_____	_____
Bearing	_____	_____	_____
Distance	_____	_____	_____

Subsequent Corner Restoration

Year surveyed 1924 By GLO
Location filed Sec. of State
Monument orig in lake Set 1x36" li. p. w/ brass cap

Evidence of Subsequent Corner Restoration

Year of search 1989 By David Landecker
Found GLO monument with rocks piled around corner.

Bearing Trees, Reference Objects

Species	<u>Mound of Stone around corner</u>	_____	_____
Diameter	_____	_____	_____
Bearing	_____	_____	_____
Distance	_____	_____	_____

Bearing Trees, Reference Objects

<u>Maple</u>	<u>Ash</u>	<u>GLO N1/4</u>
<u>10"</u>	<u>16"</u>	<u>corner</u>
<u>N16E</u>	<u>S63E</u>	<u>East</u>
<u>4.98'</u>	<u>15.68'</u>	<u>19.93'</u>

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
1989 Certificate - David Landecker
Doc. # 317228
Jun 2003 M. Landecker # 7452
Cert. of sur. shows mon. found

Remonumentation certificate prepared _____

By _____

Filed at _____

Date _____