Index No. J 4-5

# CASS COUNTY LAND CORNER RECORD

T. 143 R. 30 M. 5TH Coordinates: X _____ Y _____

MC # 19 Corner common to sections 7, 18




O = Corner

## EXISTING SURVEYS

### Original Government Survey

Year surveyed 1875

Original monument Post

### Original Evidence Found

Year of search _____ By _____

Monument found _____

### Bearing Trees

| | | | | |
|---|---|---|---|---|
| Species | Br. Oak | R. Oak | | |
| Diameter | 8" | 8" | | |
| Bearing | S32W | N55E | | |
| Distance | 24 LKS | 5 LKS | | |

### Original Bearing Trees Found

| | | | | |
|---|---|---|---|---|
| Species | | | | |
| Diameter | | | | |
| Bearing | | | | |
| Distance | | | | |

### Subsequent Corner Restoration

Year surveyed 1919 By GLO

Location filed Sec. of State

Monument orig in lake - Set 1x36" 1.P w/ brass cap T143N R30W 57/MC 5TH 1919

### Evidence of Subsequent Corner Restoration

Year of search OCT 2003 By M. Landecker #7452

Cert. of Sur. shows Mon. found

### Bearing Trees, Reference Objects

| | | | | |
|---|---|---|---|---|
| Species | Basswood | Basswood | | |
| Diameter | 12" | 5" | | |
| Bearing | N7-45W | S81W | | |
| Distance | 40 LKS | 102 LKS | | |

### Bearing Trees, Reference Objects

| | | | |
|---|---|---|---|
| | | | |
| | | | |
| | | | |
| | | | |

### Subsequent Corner Restoration

Year surveyed _____ By _____

Location filed _____

Monument _____

### Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____

Remonumentation certificate prepared _____ By _____

Filed at _____ Date _____