Index No. C17

CASS COUNTY LAND CORNER RECORD

T. 143 R. 31 M. 5TH Coordinates: X _____ Y _____

E1/4 3 Corner common to sections R3



O = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1875

Original monument lost

Bearing Trees

Species	Aspen	W. oak		
Diameter	12"	6"		
Bearing	S1W	S1E		
Distance	1840 LKS	1900 LKS		

Original Evidence Found

Year of search _____ By _____

Monument found _____

Original Bearing Trees Found

Species				
Diameter				
Bearing				
Distance				

Subsequent Corner Restoration

Year surveyed 1919 By GLO

Location filed Sec. of State

Monument Fnd S.E B.T. Set 1x36" I.P. w/brass cap.

remark tree for B.T. 1/4

Corner is on R. Bank of Crooked River 53/52

10 LKS wide 3' deep Course S.E. 1919

Bearing Trees, Reference Objects

Species	W. oak			
Diameter	14"			
Bearing	S1E			
Distance	1900 LKS			

Evidence of Subsequent Corner Restoration

Year of search _____ By _____

Bearing Trees, Reference Objects

Subsequent Corner Restoration

Year surveyed _____ By _____

Location filed

Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____

Remonumentation certificate prepared _____ By _____

Filed at _____ Date _____