

Distance _____
 Bearing _____
 Diameter _____
 Species _____

Bearing Trees, Reference Objects
 (or in marsh - no accessories available)
 1919
 54 mc
 59
 Monument set 1X36" 11.1W Brass cap THAN RAIL
 Location filed Sec. of State
 Year surveyed 1919 By GLO
 Subsequent Corner Restoration

Bearing Trees, Reference Objects

Year of search _____ By _____
 Evidence of Subsequent Corner Restoration

Distance _____
 Bearing _____
 Diameter _____
 Species _____


Bearing Trees
 750 LKS
 850 LKS
 580 W
 N 87 W
 4"
 3"
 2"
 Original monument post
 Year surveyed 1875
 Original Government Survey

Original Bearing Trees Found
 Year of search _____ By _____
 Monument found _____
 Original Evidence Found

EXISTING SURVEYS

T. 143 R. 31 M. 57H Coordinates: X _____ Y _____
 Corner common to sections 4, 9
 Index No. E 12-13

CASS COUNTY LAND CORNER RECORD



Subsequent Corner Restoration
 Year surveyed _____ By _____
 Location filed _____
 Monument _____

Evidence of Subsequent Corner Restoration Found
 Year of search _____ By _____

Remonumentation certificate prepared _____ By _____
 Filed at _____ Date _____