


Index No. 6 R5

CASS COUNTY LAND CORNER RECORD

T. 143 R. 31 M. 5TH Coordinates: X _____ Y _____
E114 12 Corner common to sections 12 AND 7-143-30



EXISTING SURVEYS

Original Government Survey

Year surveyed 1875
 Original monument Post

Original Evidence Found

Year of search _____ By _____
 Monument found _____

Bearing Trees

Species	<u>N. Pine</u>	<u>Aspen</u>	_____
Diameter	<u>24"</u>	<u>3"</u>	_____
Bearing	<u>S45E</u>	<u>S25W</u>	_____
Distance	<u>26LKS</u>	<u>12LKS</u>	_____

Original Bearing Trees Found

Species	_____	_____	_____
Diameter	_____	_____	_____
Bearing	_____	_____	_____
Distance	_____	_____	_____

Subsequent Corner Restoration

Year surveyed 1919 By GLD
 Location filed Sec. of State
 Monument Proportional position - Set 1/8 3/8" I.P. w/ brass cap
no orig evidence
5/2/57
1919

Evidence of Subsequent Corner Restoration

Year of search 1983 By Walter Curo
Set 2" x 3/8" iron pipe with brass cap.

Bearing Trees, Reference Objects

Species	<u>Aspen</u>	<u>Aspen</u>	_____
Diameter	<u>7"</u>	<u>9"</u>	_____
Bearing	<u>S83E</u>	<u>S37W</u>	_____
Distance	<u>37LKS</u>	<u>80LKS</u>	_____

Bearing Trees, Reference Objects

Species	<u>W. Oak</u>	<u>W. Oak</u>	<u>W. Oak</u>
Diameter	<u>8"</u>	<u>5"</u>	<u>8"</u>
Bearing	<u>S52W</u>	<u>S2E</u>	<u>N50E</u>
Distance	<u>59.27'</u>	<u>78.54'</u>	<u>127.32'</u>

By _____
 Date _____

Remuneration certificate prepared
 Filed at _____

Evidence of Subsequent Corner Restoration Found

Subsequent Corner Restoration

Doc. # 268850
 Certificate - Walt Curo - 1983

Monument _____
 Location filed _____

Year of search _____ By _____
 Year surveyed _____