


Index No. J 24

CASS COUNTY LAND CORNER RECORD

T. 143 R. 31 M. 5th Coordinates: X _____ Y _____
E 1/16 Corner common to sections 12, 13



EXISTING SURVEYS

Original Government Survey

Year surveyed 1919
Original monument 1x36" I.P. w/brass cap E 1/16 S 12
1919 S 13

Bearing Trees
Species J. Pine J. Pine
Diameter 8" 8"
Bearing S 36 1/2 E N 33 1/2 W
Distance 63 LKS 82 LKS

Original Evidence Found

Year of search _____ By _____
Monument found _____

Original Bearing Trees Found

Species _____
Diameter _____
Bearing _____
Distance _____

O = Corner

Subsequent Corner Restoration

Year surveyed 1982 By Walter Curo
Location filed _____
Monument Found 1" iron pipe with brass cap.

Bearing Trees, Reference Objects

Species W. Oak W. Oak W. Oak Triple
Diameter 8" 8" 6"-8"-8"
Bearing N 35 W N 20 E S 85 W
Distance 17.66' 22.28' 24.92'

Evidence of Subsequent Corner Restoration

Year of search _____ By _____

Bearing Trees, Reference Objects

Species _____
Diameter _____
Bearing _____
Distance _____

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____

Certificate - Walter Curo 1983
Doc. # 208839

Remonumentation certificate prepared _____ By _____
Filed at _____ Date _____