


Index No. \_\_\_\_\_

CASS COUNTY LAND CORNER RECORD

T. \_\_\_\_\_ R. \_\_\_\_\_ M. \_\_\_\_\_ Coordinates: X \_\_\_\_\_ Y \_\_\_\_\_

Corner common to sections \_\_\_\_\_



= Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed \_\_\_\_\_  
Original monument \_\_\_\_\_

Original Evidence Found

Year of search \_\_\_\_\_ by \_\_\_\_\_  
Monument found \_\_\_\_\_

Bearing Trees

Species \_\_\_\_\_  
Diameter \_\_\_\_\_  
Bearing \_\_\_\_\_  
Distance \_\_\_\_\_

Original Bearing Trees Found

Species \_\_\_\_\_  
Diameter \_\_\_\_\_  
Bearing \_\_\_\_\_  
Distance \_\_\_\_\_

Subsequent Corner Restoration

Year surveyed \_\_\_\_\_ By \_\_\_\_\_  
Location filed:  
Monument:

Evidence of Subsequent Corner Restoration

Year of search \_\_\_\_\_ By \_\_\_\_\_  
Location filed:  
Monument:

Bearing Trees, Reference Objects

Species \_\_\_\_\_  
Diameter \_\_\_\_\_  
Bearing \_\_\_\_\_  
Distance \_\_\_\_\_

Bearing Trees, Reference Objects

Species \_\_\_\_\_  
Diameter \_\_\_\_\_  
Bearing \_\_\_\_\_  
Distance \_\_\_\_\_


Subsequent Corner Restoration

Year surveyed \_\_\_\_\_ By \_\_\_\_\_  
Location filed:  
Monument:

Evidence of Subsequent Corner Restoration Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
Location filed:  
Monument:

T. 143 R. 31 M. 5TH Coordinates: X \_\_\_\_\_ Y \_\_\_\_\_  
NE 17 Corner common to sections 8, 9, 16, 17



EXISTING SURVEYS

Original Government Survey			
Year surveyed <u>1875</u>			
Original monument <u>post</u>			
Species	Bearing Trees		
<u>N. Pine</u>	<u>N. Pine</u>	<u>Aspen</u>	<u>Aspen</u>
Diameter <u>6"</u>	<u>6"</u>	<u>5"</u>	<u>4"</u>
Bearing <u>N38E</u>	<u>S53E</u>	<u>N42W</u>	<u>S30W</u>
Distance <u>24 Lks</u>	<u>65 Lks</u>	<u>215 Lks</u>	<u>230 Lks</u>

Original Evidence Found	
Year of search _____	By _____
Monument found _____	
Original Bearing Trees Found	
Species _____	_____
Diameter _____	_____
Bearing _____	_____
Distance _____	_____

O = Corner

Subsequent Corner Restoration

Year surveyed 1919 By GLO  
 Location filed Sec. of State  
 Monument End 2 1/2" Galv. I.P. and NE & SE B.T.S  
Set 2x36" I.P. w/ brass cap. T143N R31W  
 Remark B.T.S. for new B.T.S. SB | SE  
517 | 516

Evidence of Subsequent Corner Restoration

Year of search 1977 By DNR-Engineering  
Map's preliminary certificate in file

Bearing Trees, Reference Objects 1919

Species	Bearing Trees, Reference Objects	
<u>N. Pine</u>	<u>N. Pine</u>	_____
Diameter <u>18"</u>	<u>18"</u>	_____
Bearing <u>N40E</u>	<u>S51E</u>	_____
Distance <u>24 Lks</u>	<u>65 Lks</u>	_____

Bearing Trees, Reference Objects

_____	_____	_____
_____	_____	_____
_____	_____	_____
_____	_____	_____

Date \_\_\_\_\_

By \_\_\_\_\_

Remuneration certificate prepared \_\_\_\_\_

Filed at \_\_\_\_\_

Subsequent Corner Restoration  
 1935 By Ann Huy Dept.  
 Location filed in map in recorder's office - w/ letter to Cass Lake  
iron pipe & brass cap  
 July 2004 R. Cornell Sr. # 43415  
 cert. of sur. shows mon. found  
 April 1917  
Trap Road Order shows no survey

Evidence of Subsequent Corner Restoration Found

Year of search \_\_\_\_\_ By \_\_\_\_\_