


Index No. K 23

CASS COUNTY LAND CORNER RECORD

T. 143 R. 31 M. 5TH Coordinates: X _____ Y _____
C.N. 114 Corner common to sections 13



○ = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1919
Original monument 1x36" 1/2" w/ brass cap N 116 1/2° S 13
1919

Original Evidence Found

Year of search _____ By _____
Monument found _____

Bearing Trees

Species Jilene Jilene _____
Diameter 8" 9" _____
Bearing N 19 E S 22 E _____
Distance 25 Lks 49 Lks _____

Original Bearing Trees Found

Species _____
Diameter _____
Bearing _____
Distance _____

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration

Year of search _____ By _____

Bearing Trees, Reference Objects

Species _____
Diameter _____
Bearing _____
Distance _____

Bearing Trees, Reference Objects

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____

Re monumentation certificate prepared _____ By _____
Filed at _____ Date _____