


Index No. N1

CASS COUNTY LAND CORNER RECORD

T. 143 R. 31 M. 5TH Coordinates: X \_\_\_\_\_ Y \_\_\_\_\_  
NW19 Corner common to sections 18,19



EXISTING SURVEYS

Original Government Survey

Year surveyed 1874  
Original monument Post

Original Evidence Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
Monument found \_\_\_\_\_

Bearing Trees

Species	<u>W. Pine</u>	<u>W. Pine</u>	<u>W. Pine</u>	<u>W. Pine</u>
Diameter	<u>25"</u>	<u>25"</u>	<u>20"</u>	<u>20"</u>
Bearing	<u>S40E</u>	<u>N8E</u>	<u>N83W</u>	<u>S55W</u>
Distance	<u>47Lks</u>	<u>19Lks</u>	<u>44Lks</u>	<u>50Lks</u>

Original Bearing Trees Found

Species	_____	_____	_____	_____
Diameter	_____	_____	_____	_____
Bearing	_____	_____	_____	_____
Distance	_____	_____	_____	_____

Subsequent Corner Restoration

Year surveyed Jan. 31, 1995 By T. Freeman #21367  
Location filed \_\_\_\_\_  
Monument Cent. of Svc. Shows mon. Found

Evidence of Subsequent Corner Restoration

Year of search \_\_\_\_\_ By \_\_\_\_\_

Bearing Trees, Reference Objects

Species	_____	_____	_____	_____
Diameter	_____	_____	_____	_____
Bearing	_____	_____	_____	_____
Distance	_____	_____	_____	_____

Bearing Trees, Reference Objects

Species	_____	_____	_____	_____
Diameter	_____	_____	_____	_____
Bearing	_____	_____	_____	_____
Distance	_____	_____	_____	_____

Remuneration certificate prepared \_\_\_\_\_ By \_\_\_\_\_ Date \_\_\_\_\_  
Filed at \_\_\_\_\_

---

---

---

---

---

---

---

---

---

---

---

---

---

---

---

---

---

---

---

---

---

---

---

---



---

---

---

---

---

---

---

---

---

---

---

---

---

---

---

---

---

---

---

---

---

---

---

---

Evidence of Subsequent Corner Restoration Found

Subsequent Corner Restoration

Year of search \_\_\_\_\_ By \_\_\_\_\_

Year surveyed \_\_\_\_\_ Location filed \_\_\_\_\_ Monument \_\_\_\_\_