


Index No. N 10-11

CASS COUNTY LAND CORNER RECORD

T. 143 R. 31 M. 5TH Coordinates: X _____ Y _____
MC # 12 Corner common to sections 16, 21



○ = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1875
Original monument Post

Bearing Trees

Species	<u>Oak</u>	<u>Birch</u>	_____
Diameter	<u>4"</u>	<u>3"</u>	_____
Bearing	<u>S 68W</u>	<u>N 14E</u>	_____
Distance	<u>71 LKS</u>	<u>20 LKS</u>	_____

Original Evidence Found

Year of search _____ By _____
Monument found _____

Original Bearing Trees Found

Species	_____	_____	_____
Diameter	_____	_____	_____
Bearing	_____	_____	_____
Distance	_____	_____	_____

Subsequent Corner Restoration

Year surveyed 1919 By GLD
Location filed Sec. of State
Monument Set (x 36" IIP. w/ Brass cap
T 143N R 31W
S 16 7/8 MC
S 21
1919

Bearing Trees, Reference Objects

Species	<u>W. Oak</u>	<u>Poplar</u>	_____
Diameter	<u>6"</u>	<u>10"</u>	_____
Bearing	<u>N 85 1/4 W</u>	<u>S 84 3/4 W</u>	_____
Distance	<u>62 LKS</u>	<u>180 LKS</u>	_____

Evidence of Subsequent Corner Restoration

Year of search _____ By _____

Bearing Trees, Reference Objects

Species	_____	_____	_____
Diameter	_____	_____	_____
Bearing	_____	_____	_____
Distance	_____	_____	_____

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
PLAT - KING'S ISLAND PARK
EDWIN RANKIN 1963

Remonumentation certificate prepared _____ By _____
Filed at _____ Date _____