


Index No. N 1344

CASS COUNTY LAND CORNER RECORD

T. 143 R. 31 M. 5TH Coordinates: X \_\_\_\_\_ Y \_\_\_\_\_  
MC # 29 Corner common to sections 15, 22



EXISTING SURVEYS

Original Government Survey

Year surveyed 1875  
Original monument Post

Original Evidence Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
Monument found \_\_\_\_\_

Species	Bearing	Trees
<u>W. Oak</u>	<u>W. Oak</u>	
<u>10"</u>	<u>10"</u>	
<u>N48E</u>	<u>South</u>	
<u>53 LKS</u>	<u>14 LKS</u>	

Original Bearing Trees Found

Species	Diameter	Bearing	Distance
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

○ = Corner

Subsequent Corner Restoration

Year surveyed 1919 By GLO  
Location filed Sec. of State  
Monument End NE BIT Stub; stump of South BIT.  
Set 1x36" 1 1/2" w/brass cap  
7143N R 31W  
MC 1515  
1522  
1919

Evidence of Subsequent Corner Restoration

Year of search \_\_\_\_\_ By \_\_\_\_\_

Bearing Trees, Reference Objects

Species	Bearing	Reference Objects
<u>oak stub</u>	<u>R. oak</u>	
<u>14"</u>	<u>10"</u>	
<u>N36E</u>	<u>S574E</u>	
<u>53 LKS</u>	<u>319 LKS</u>	

*Remark 6/19/19*

Bearing Trees, Reference Objects

Species	Diameter	Bearing	Distance
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

Subsequent Corner Restoration

Year surveyed \_\_\_\_\_ By \_\_\_\_\_  
Location filed \_\_\_\_\_  
Monument \_\_\_\_\_

Evidence of Subsequent Corner Restoration Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
PLAT - KING'S ISLAND PARK  
EDWIN RANKIN 1963

Remonumentation certificate prepared \_\_\_\_\_ By \_\_\_\_\_  
Filed at \_\_\_\_\_ Date \_\_\_\_\_