Index No. N7

CASS COUNTY LAND CORNER RECORD

T. 143 R. 31 M. 5TH Coordinates: X _____ Y _____

N1/4 20 Corner common to sections 17,20



EXISTING SURVEYS

Original Government Survey

Year surveyed 1875

Original monument Post

Original Evidence Found

Year of search _____ By _____

Monument found _____

Bearing Trees

Species	Aspen	Lynn		
Diameter	8"	12"		
Bearing	N55W	S59W		
Distance	20 lks	14 lks		

Original Bearing Trees Found

Species				
Diameter				
Bearing				
Distance				

Subsequent Corner Restoration

Year surveyed 1919 By GLO

Location filed Sec. of State

Monument Set 1x36" Illinois brass cap 1/4 517 / 520 1919

no orig evidence

Evidence of Subsequent Corner Restoration

Year of search 1925 By Minn Hwy Dept.

R/W map in Recorder's office - Walker to Cass Lake

1" iron pipe & brass cap 1495.4' W. of ℄

Bearing Trees, Reference Objects

Species	Br. Oak	Burned W. oak stump		
Diameter	12"	24"		
Bearing	N34 1/4E	S61 1/4E		
Distance	220 lks	43 lks		

Bearing Trees, Reference Objects

Remonumentation certificate prepared _____ By _____ Date _____

Filed at _____

Subsequent Corner Restoration

Year surveyed _____ By _____

Location filed _____

Monument

6/2002 CCSO

found 1/2" bolt / pt. down 0.4' ± S. of ℄ CR. 3 ± W. of ℄ Harmony Rd.

10" Maple S33°E 51.3' dbl hd acl

± 6" dead post N47°W 39.57' 8d / bottle cap

5" Ash N [redacted]2°W 93.13' dbl hd acl

10" Juneberry N64°E 111.05' dbl hd acl

Meadows Township #31367

East of Stanley Shores PL not fenced

Evidence of Subsequent Corner Restoration

Year of search _____ By _____