


Index No. R 25

CASS COUNTY LAND CORNER RECORD

143 R. 31 M. 5TH Coordinates: X \_\_\_\_\_ Y \_\_\_\_\_  
NE 25 Corner common to sections 24, 25 AND 19, 30 - 193-30



EXISTING SURVEYS

**Original Government Survey**  
 Year surveyed 1875  
 Original monument Post

| Bearing Trees |         |         |         |
|---------------|---------|---------|---------|
| Species       | Bc. Oak | R. Oak  | R. Oak  |
| Diameter      | 8"      | 8"      | 12"     |
| Bearing       | N37E    | S44W    | N41W    |
| Distance      | 563 LKS | 244 LKS | 360 LKS |

**Original Evidence Found**  
 Year of search \_\_\_\_\_ By \_\_\_\_\_  
 Monument found \_\_\_\_\_

**Original Bearing Trees Found**

| Species | Diameter | Bearing | Distance |
|---------|----------|---------|----------|
|         |          |         |          |
|         |          |         |          |
|         |          |         |          |
|         |          |         |          |

**Subsequent Corner Restoration**  
 Year surveyed 1919 By GLO  
 Location filed Sec. of State  
 Monument Set 2x36" lip. w/brass cap 7143N  
R31W R30W  
S24 1/2 S19  
S25 1/2 S30  
1919

**Evidence of Subsequent Corner Restoration**  
 Year of search \_\_\_\_\_ By \_\_\_\_\_

**Bearing Trees, Reference Objects**  
 Species Birch Poplar Poplar W. Oak  
 Diameter 6" 8" 6" 8"  
 Bearing N74 3/4 E S57 1/4 E S56 1/2 W N61 1/2 W  
 Distance 30 LKS 18 LKS 21 LKS 15 LKS

**Bearing Trees, Reference Objects**

**Subsequent Corner Restoration**  
 Year surveyed \_\_\_\_\_ By \_\_\_\_\_  
 Location filed \_\_\_\_\_  
 Monument \_\_\_\_\_

**Evidence of Subsequent Corner Restoration Found**  
 Year of search \_\_\_\_\_ By \_\_\_\_\_  
PLAT - CHIPPEWA BEACH  
HAROLD CURD 1956

Remonumentation certificate prepared \_\_\_\_\_ By \_\_\_\_\_  
 Filed at \_\_\_\_\_ Date \_\_\_\_\_