


Index No. T 20

CASS COUNTY LAND CORNER RECORD

T. 143 R. 31 M. 5TH Coordinates: X \_\_\_\_\_ Y \_\_\_\_\_  
C.E. 116 Corner common to sections 26



EXISTING SURVEYS

Original Government Survey

Year surveyed 1919  
Original monument 1X36" 1lb. w/brass cap E 116  
526  
1919

Original Evidence Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
Monument found \_\_\_\_\_

Bearing Trees

Species R. Oak R. Oak \_\_\_\_\_  
Diameter 12" 6" \_\_\_\_\_  
Bearing S43 1/2 W N62 W \_\_\_\_\_  
Distance 44 US 27 US \_\_\_\_\_

Original Bearing Trees Found

Species \_\_\_\_\_  
Diameter \_\_\_\_\_  
Bearing \_\_\_\_\_  
Distance \_\_\_\_\_

Subsequent Corner Restoration

Year surveyed \_\_\_\_\_ By \_\_\_\_\_  
Location filed \_\_\_\_\_  
Monument \_\_\_\_\_

Evidence of Subsequent Corner Restoration

Year of search \_\_\_\_\_ By \_\_\_\_\_

Bearing Trees, Reference Objects

Species \_\_\_\_\_  
Diameter \_\_\_\_\_  
Bearing \_\_\_\_\_  
Distance \_\_\_\_\_

Bearing Trees, Reference Objects

\_\_\_\_\_

Subsequent Corner Restoration

Year surveyed \_\_\_\_\_ By \_\_\_\_\_  
Location filed \_\_\_\_\_  
Monument \_\_\_\_\_

Evidence of Subsequent Corner Restoration Found

Year of search \_\_\_\_\_ By \_\_\_\_\_

Remonumentation certificate prepared \_\_\_\_\_ By \_\_\_\_\_  
Filed at \_\_\_\_\_ Date \_\_\_\_\_