

Bearing Trees, Reference Objects

Year of search _____ By _____

Evidence of Subsequent Corner Restoration

Bearing Trees, Reference Objects

Year surveyed _____ Location filed _____ Monument _____

Subsequent Corner Restoration

Original Evidence Found

Year of search _____ Monument found _____

Original Bearing Trees Found


Species _____ Diameter _____ Bearing _____ Distance _____

Original Government Survey

Year surveyed 1876 Original monument Post

Bearing Trees

Species _____ Diameter NO TIES _____ Bearing _____ Distance _____



EXISTING SURVEYS

Original Evidence Found

Year of search _____ Monument found _____

Corner common to sections 4, 9

Coordinates: X _____ Y _____

T. 144 N. R. 25 M. 5TH

CASS COUNTY LAND CORNER RECORD

Index No. E 11

Subsequent Corner Restoration

Year surveyed _____ By _____

Location filed _____

Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____

Certificate - Jim Parker - 1985

Set lost - 5/8" x 11' aluminum rod w/cap

Steel sign post west 4.80'

Doc. # 281671

Remonumentation certificate prepared _____ By _____

Filed at _____ Date _____