Index No. E15

CASS COUNTY LAND CORNER RECORD

T. 144 R. 25 M. 5TH Coordinates: X _____ Y _____

N1/4 10 Corner common to sections 3/10



O = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1876

Original monument lost

Original Evidence Found

Year of search _____ By _____

Monument found _____

Bearing Trees

Species				
Diameter				
Bearing				
Distance				

Original Bearing Trees Found

Species				
Diameter				
Bearing				
Distance				

Subsequent Corner Restoration

Year surveyed _____ By _____

Location filed _____

Monument _____

Evidence of Subsequent Corner Restoration

Year of search _____ By _____

Bearing Trees, Reference Objects

Species				
Diameter				
Bearing				
Distance				

Bearing Trees, Reference Objects

Subsequent Corner Restoration

Year surveyed _____ By _____

Location filed _____

Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____

Certificate - Jim Parker - 1985
set lost - 5/8" x 11' aluminum rod w/cap
Steel sign post East 4.30'
Doc. # 281672

Remonumentation certificate prepared _____ By _____

Filed at _____ Date _____