Index No. 621

CASS COUNTY LAND CORNER RECORD

T. 144 R. 25 M. 5TH Coordinates: X _____ Y _____

E1/4 11 Corner common to sections 11,12



EXISTING SURVEYS

Original Government Survey

Year surveyed 1876

Original monument lost

Bearing Trees

Species	No trees			
Diameter				
Bearing				
Distance				

Original Evidence Found

Year of search _____ By _____

Monument found _____

Original Bearing Trees Found

Species				
Diameter				
Bearing				
Distance				

Subsequent Corner Restoration

Year surveyed _____ By _____

Location filed _____

Monument _____

Bearing Trees, Reference Objects

Species				
Diameter				
Bearing				
Distance				

Evidence of Subsequent Corner Restoration

Year of search _____ By _____

Bearing Trees, Reference Objects

Subsequent Corner Restoration

Year surveyed _____ By _____

Location filed

Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____

Certificate - Jim Parker - 1985
Set lost - set 5/8"x 8' aluminum rod w/cap
Steel sign post North 3.90'
Doc. # 2816677

Remonumentation certificate prepared _____ By _____

Filed at _____ Date _____