


144 R. 25 M. 5th Coordinates: X _____ Y _____
SE 1/4 Corner common to sections 9



EXISTING SURVEYS																					
<p style="text-align: center;">Original Government Survey</p> <p>Year surveyed _____</p> <p>Original monument _____</p> <p style="text-align: center;">Bearing Trees</p> <p>Species _____</p> <p>Diameter <u>NOT SET IN ORIGINAL SURVEY</u></p> <p>Bearing _____</p> <p>Distance _____</p> <p style="text-align: center;">Subsequent Corner Restoration</p> <p>Year surveyed <u>1985</u> By <u>USFS</u></p> <p>Location filed <u>Corner Certificate - Doc # 285580</u></p> <p>Monument <u>Set 5/8" x 1/8" aluminum rod w/ stamped aluminum cap. up 18"</u></p> <p style="text-align: center;">Bearing Trees, Reference Objects</p> <table border="1" style="width:100%; border-collapse: collapse;"> <tr> <td>Species</td> <td><u>Cedar</u></td> <td><u>Cedar</u></td> <td><u>Tamarack</u></td> <td><u>Metal Posts</u></td> </tr> <tr> <td>Diameter</td> <td><u>7.2"</u></td> <td><u>6.0"</u></td> <td><u>8.1"</u></td> <td><u>8' long</u></td> </tr> <tr> <td>Bearing</td> <td><u>N8E</u></td> <td><u>N21W</u></td> <td><u>S23E</u></td> <td><u>S; W</u></td> </tr> <tr> <td>Distance</td> <td><u>42.58'</u></td> <td><u>36.38'</u></td> <td><u>57.63'</u></td> <td><u>3'</u></td> </tr> </table>	Species	<u>Cedar</u>	<u>Cedar</u>	<u>Tamarack</u>	<u>Metal Posts</u>	Diameter	<u>7.2"</u>	<u>6.0"</u>	<u>8.1"</u>	<u>8' long</u>	Bearing	<u>N8E</u>	<u>N21W</u>	<u>S23E</u>	<u>S; W</u>	Distance	<u>42.58'</u>	<u>36.38'</u>	<u>57.63'</u>	<u>3'</u>	<p style="text-align: center;">Original Evidence Found</p> <p>Year of search _____ By _____</p> <p>Monument found _____</p> <p style="text-align: center;">Original Bearing Trees Found</p> <p>Species _____</p> <p>Diameter _____</p> <p>Bearing _____</p> <p>Distance _____</p> <p style="text-align: center;">Evidence of Subsequent Corner Restoration</p> <p>Year of search _____ By _____</p> <p style="text-align: center;">Bearing Trees, Reference Objects</p> <p>Species _____</p> <p>Diameter _____</p> <p>Bearing _____</p> <p>Distance _____</p>
Species	<u>Cedar</u>	<u>Cedar</u>	<u>Tamarack</u>	<u>Metal Posts</u>																	
Diameter	<u>7.2"</u>	<u>6.0"</u>	<u>8.1"</u>	<u>8' long</u>																	
Bearing	<u>N8E</u>	<u>N21W</u>	<u>S23E</u>	<u>S; W</u>																	
Distance	<u>42.58'</u>	<u>36.38'</u>	<u>57.63'</u>	<u>3'</u>																	

Subsequent Corner Restoration	Evidence of Subsequent Corner Restoration Found
<p>Year surveyed _____ By _____</p> <p>Location filed _____</p> <p>Monument _____</p>	<p>Year of search _____ By _____</p> <p><u>Certificate - Ken Whitehorn - USFS - 1985</u></p>