

Species _____
Diameter _____
Bearing _____
Distance _____

Bearing Trees, Reference Objects

Bearing Trees, Reference Objects

Monument _____

Location filed _____

By _____

Year of search _____

By _____

Evidence of Subsequent Corner Restoration

Subsequent Corner Restoration

Distance _____

Bearing _____

Diameter _____

Species _____

Cedar 10"
Cedar 10"
NSW
12LKS
15LKS

Bearing Trees

Distance _____

Bearing _____

Diameter _____

Species _____

Original Bearing Trees Found

Original Government Survey

Year surveyed 1876
Original monument lost

Year of search _____

Original Evidence Found

EXISTING SURVEYS

Corner common to sections 9/16

Coordinates: X M 5TH 144 R 25

Y _____

CASS COUNTY LAND CORNER RECORD

Index No. 511

Subsequent Corner Restoration

Evidence of Subsequent Corner Restoration Found

Year surveyed _____ By _____

Location filed _____

Monument _____

Year of search _____ By _____

Certificate - Jim Parker - 1985
Set obliterated from 1900 Corp info - set
2 1/2" l.p. w/ marked brass cap
7" Balsam N80°E 2.35'
6" Ash S13°E 34.17'
Doc. # 281684

Remonumentation certificate prepared _____

By _____

Filed at _____

Date _____

