

Species  
Diameter  
Bearing  
Distance

Bearing Trees, Reference Objects

Monument  
Location filed  
Year surveyed

By

Subsequent Corner Restoration

Species  
Diameter  
Bearing  
Distance

Bearing Trees

Year surveyed  
Original monument

1876  
Post

Original Government Survey

EXISTING SURVEYS

Index No. 515  
T. 144 R. 25 M. 574 Coordinates: X  
Corner common to sections 10/15

CASS COUNTY LAND CORNER RECORD

Species  
Diameter  
Bearing  
Distance

Bearing Trees, Reference Objects

Monument  
Location filed  
Year surveyed

By

Evidence of Subsequent Corner Restoration


Species  
Diameter  
Bearing  
Distance

Original Bearing Trees Found

Year of search  
Monument found

By

Original Evidence Found



Subsequent Corner Restoration

Year surveyed \_\_\_\_\_ By \_\_\_\_\_  
Location filed \_\_\_\_\_  
Monument \_\_\_\_\_

Evidence of Subsequent Corner Restoration Found

Year of search \_\_\_\_\_ By \_\_\_\_\_

Certificate - Jim Parker - 1985  
Set obliterated - set 5/8" x 8' aluminum rod  
w/cap  
steel fence post South 4.30'  
Doc. # 281710

Remonumentation certificate prepared \_\_\_\_\_ By \_\_\_\_\_  
Filed at \_\_\_\_\_ Date \_\_\_\_\_