

Index No. 582-23


CASS COUNTY LAND CORNER RECORD

T. 144 R. 25 M. 5TH Coordinates: X 12/13 Y _____
 Corner common to sections 12/13
 MC # 48

EXISTING SURVEYS

Original Evidence Found _____
 Year of search _____ By _____
 Monument found _____

Original Bearing Trees Found _____
 Species _____
 Diameter _____
 Bearing _____
 Distance _____



Original Government Survey _____
 Year surveyed 1876
 Original monument post
 Bearing Trees No trees

Species _____
 Diameter _____
 Bearing _____
 Distance _____

Subsequent Corner Restoration _____
 Year surveyed _____ By _____
 Location filed _____
 Monument _____

Bearing Trees, Reference Objects _____
 Species _____
 Diameter _____
 Bearing _____
 Distance _____

Evidence of Subsequent Corner Restoration

Original Bearing Trees Found _____
 Species _____
 Diameter _____
 Bearing _____
 Distance _____

Year of search _____ By _____
 Bearing Trees, Reference Objects _____

Subsequent Corner Restoration

Evidence of Subsequent Corner Restoration Found

Year surveyed _____ By _____
 Location filed _____
 Monument _____

Year of search _____ By _____

Remonumentation certificate prepared _____

By _____

Filed at _____

Date _____