

Species
Diameter
Bearing
Distance

Bearing Trees, Reference Objects

Bearing Trees, Reference Objects

Monument

Location filed

By

Year of search

By

Evidence of Subsequent Corner Restoration

Subsequent Corner Restoration

Distance

Bearing

Diameter

Species

Bearing Trees

Distance

Bearing

Diameter

Species

Original Bearing Trees Found

Monument found

Year of search

Original Evidence Found

Original Government Survey

EXISTING SURVEYS

Coordinates: X

Corner common to sections

Y

CASS COUNTY LAND CORNER RECORD

Index No. 113

T. 144 R. 25 M. 57H

E 1/4 1/6

Original monument lost

Year surveyed 1876

1876

1745

N53E

6"

Jun


2245

N63W

6"

Jun

O = Corner



Subsequent Corner Restoration

Evidence of Subsequent Corner Restoration Found

Year surveyed _____ By _____

Year of search _____ By _____

Location filed _____

Monument _____

Certificate - Jim Parker - 1985
 Set lost - 5/8" x 5' long aluminum rod w/cap
 5" Cedar N60°E 16.74'
 4" Spruce N35°W 21.00'
 Doc. # 281717

Re monumentation certificate prepared _____

By _____

Filed at _____

Date _____