

Species \_\_\_\_\_  
Diameter \_\_\_\_\_  
Bearing \_\_\_\_\_  
Distance \_\_\_\_\_

Bearing Trees, Reference Objects

Monument \_\_\_\_\_

Location filed \_\_\_\_\_

Year surveyed \_\_\_\_\_ By \_\_\_\_\_

Subsequent Corner Restoration

Species 10m \_\_\_\_\_  
Diameter 5" \_\_\_\_\_  
Bearing Spruce \_\_\_\_\_  
Distance 16LKS \_\_\_\_\_

Bearing Trees

Year surveyed 1876

Post

Original Government Survey

Original Evidence Found

Year of search \_\_\_\_\_ By \_\_\_\_\_

Monument found \_\_\_\_\_

Original Bearing Trees Found

EXISTING SURVEYS


CASS COUNTY LAND CORNER RECORD

Index No. 221

T. 144 R. 25 M. 57N Coordinates: X \_\_\_\_\_ Y \_\_\_\_\_

Corner common to sections 13/14

O = Corner



Subsequent Corner Restoration

Evidence of Subsequent Corner Restoration Found

Year surveyed \_\_\_\_\_ By \_\_\_\_\_

Location filed \_\_\_\_\_

Monument \_\_\_\_\_

Year of search \_\_\_\_\_ By \_\_\_\_\_

Certificate - Jim Parker - 1985  
set obliterated from 1900 Corp mfg. - set 5/8" x 8'  
aluminum rod w/cap  
3" Tamarack S30E 27.14'  
3" Tamarack S31W 13.08'  
Doc # 281800

Remonumentation certificate prepared \_\_\_\_\_

By \_\_\_\_\_

Filed at \_\_\_\_\_

Date \_\_\_\_\_