

Species
Diameter
Bearing
Distance

Bearing Trees, Reference Objects

Monument

Location filed

By

Year surveyed

Subsequent Corner Restoration

Distance

Bearing

Diameter

Species

Bearing Trees

Original monument

Year surveyed

Original Government Survey

EXISTING SURVEYS

Coordinates: X 15,82 Y 14,82
T. 144 R. 25 M. 57H
Corner common to sections 15,82 14,82

CASS COUNTY LAND CORNER RECORD

Index No. 115

Bearing Trees, Reference Objects

Year of search

Evidence of Subsequent Corner Restoration

Distance

Bearing

Diameter

Species


Original Bearing Trees Found

Monument found

Year of search

Original Evidence Found

O = Corner



Subsequent Corner Restoration

Year surveyed

By

Location filed

Monument

Evidence of Subsequent Corner Restoration Found

Year of search

By

Certificate - Jim Parker - 1985
Set lost - 5 1/2" x 5" aluminum rod w/cap
6" Tam N20W 1.18
7" Cedar S70W 10.76'
Doc # 281808

Remonumentation certificate prepared

By

Filed at

Date