

Species
Diameter
Bearing
Distance

Bearing Trees, Reference Objects

Monument

Location filed

Year surveyed _____ By _____

Subsequent Corner Restoration

Distance

Bearing

Diameter

Species

Species Willow
Diameter 12"
Bearing S 12 E
Distance 5 LKS
Species Willow
Diameter 12"
Bearing N 67 W
Distance 23 LKS

Bearing Trees

Original monument

Post

Year surveyed 1876

Original Government Survey

EXISTING SURVEYS

Coordinates: X 144 R. 25 M. 577 Y 1819
Corner common to sections 1819
N 1/4 19

CASS COUNTY LAND CORNER RECORD

Index No. N 3

Subsequent Corner Restoration

Year surveyed _____ By _____

Location filed _____

Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____

Certificate - Tim Parker - 1985

Set lost - 2' 2" I.P. w/cap

9" W. Oak N 21 E 29.40'

11" Basswood N 86 W 19.49'


Doc. # 281802

Re monumentation certificate prepared _____

By _____

Filed at _____

Date _____



O = Corner

Original Bearing Trees Found

Species

Diameter

Bearing

Distance

Evidence of Subsequent Corner Restoration

Year of search _____ By _____

Bearing Trees, Reference Objects