

Species
Diameter
Bearing
Distance

Bearing Trees, Reference Objects

Bearing Trees, Reference Objects

Monument

Location filed

By

Year of search

By

Subsequent Corner Restoration

Evidence of Subsequent Corner Restoration

Species
Diameter
Bearing
Distance

Bearing Trees

Species	Cedar	Cedar	Cedar	Cedar
Diameter	12"	12"	12"	12"
Bearing	N60E	N64W	N64W	N60E
Distance	12 LKS	15 LKS	24 LKS	26 LKS

Original Bearing Trees Found

EXISTING SURVEYS

Original Government Survey


Original Evidence Found

Year of search

By

Monument found

O = Corner



CASS COUNTY LAND CORNER RECORD

Index No. **N5**

T. **144** R. **25** M. **57A** Coordinates: X **17181920** Y **19** Corner common to sections **NE 19**

Evidence of Subsequent Corner Restoration Found

Subsequent Corner Restoration

Year of search _____ By _____

Year surveyed _____ By _____

Location filed _____

Monument _____

Certificate - Jim Parker - 1985
 Set by double proportion - 2 1/2" i.p. w/cap
 9" Ash N80E 63.67'
 8" Balsam 542E 44.47'
 7" Balsam 536W 30.72'
 11" Aspen N55W 46.93'
 Doc. # 281803

Remuneration certificate prepared _____

By _____

Filed at _____

Date _____