

Species \_\_\_\_\_  
 Diameter \_\_\_\_\_  
 Bearing \_\_\_\_\_  
 Distance \_\_\_\_\_

Bearing Trees, Reference Objects

Monument \_\_\_\_\_

Year surveyed \_\_\_\_\_  
 Location filed \_\_\_\_\_

By \_\_\_\_\_

Subsequent Corner Restoration

Species Birch 5"  
 Diameter 5.58E  
 Bearing N43W  
 Distance 6LKS

Bearing Trees  
 Species Birch 6"  
 Diameter 6LKS  
 Bearing 11LKS  
 Distance \_\_\_\_\_

Year surveyed 1876  
 Original monument lost

Original Government Survey

Year of search \_\_\_\_\_  
 Monument found \_\_\_\_\_

Original Evidence Found

EXISTING SURVEYS

Index No. N7  
 T. 144 R. 25 M. 5TH Coordinates: X \_\_\_\_\_ Y \_\_\_\_\_  
 Corner common to sections 17, 20

CASS COUNTY LAND CORNER RECORD

Subsequent Corner Restoration


Year surveyed \_\_\_\_\_ By \_\_\_\_\_  
 Location filed \_\_\_\_\_  
 Monument \_\_\_\_\_

Evidence of Subsequent Corner Restoration Found

Year of search \_\_\_\_\_ By \_\_\_\_\_

Certificate - Jim Parker - 1985  
Set lost - 2 1/2" I.P. w/ brass cap  
11" Balsam N10°E 62.03'  
8" SPRUCE N75E 42.76'  
Doc. # 281804

Remonumentation certificate prepared \_\_\_\_\_ By \_\_\_\_\_  
 Filed at \_\_\_\_\_ Date \_\_\_\_\_



O = Corner

Original Bearing Trees Found

Species \_\_\_\_\_  
 Diameter \_\_\_\_\_  
 Bearing \_\_\_\_\_  
 Distance \_\_\_\_\_

Evidence of Subsequent Corner Restoration

Year of search \_\_\_\_\_  
 By \_\_\_\_\_

Bearing Trees, Reference Objects