

Species _____
Diameter _____
Bearing _____
Distance _____

Bearing Trees, Reference Objects

Monument _____

Location filed _____

Year surveyed _____ By _____

Subsequent Corner Restoration

Species Balsam 8"
Diameter 1706
Bearing N 88 W
Distance 645

Bearing Trees

Year surveyed 1876
Original monument lost

Original Government Survey

EXISTING SURVEYS

T. 144 R. 25 M. 5TH Coordinates: X 2223 Y _____
Corner common to sections 2223 214 22

CASS COUNTY LAND CORNER RECORD

Index No. 917

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____

Certificate - Jim Parker - 1985
Set lost 2 1/2" l.p. w/ brass cap.
8" Ash S 81° E 15.50'
6" Twin Cedar S 55° W 29.30'
Doc. # 281952

Bearing Trees, Reference Objects


Evidence of Subsequent Corner Restoration

Species _____
Diameter _____
Bearing _____
Distance _____

Original Bearing Trees Found

Year of search _____ By _____
Monument found _____
Original Evidence Found _____

O = Corner



Remonumentation certificate prepared _____ By _____

Filed at _____ Date _____