


Index No. R.0-11.0

CASS COUNTY LAND CORNER RECORD

T. 144 R. 25 M. 5th Coordinates: X _____ Y _____

N 1/4 28 Corner common to sections 21, 28



EXISTING SURVEYS

Original Government Survey

Year surveyed 1876
Original monument Post

Original Evidence Found

Year of search _____ by _____
Monument found _____

Bearing Trees

Species	<u>Balsam</u>	<u>Ironwood</u>
Diameter	<u>8"</u>	<u>5"</u>
Bearing	<u>N 53° W</u>	<u>S 4° E</u>
Distance	<u>38 links</u>	<u>34 links</u>

Original Bearing Trees Found

Species	_____	_____	_____
Diameter	_____	_____	_____
Bearing	_____	_____	_____
Distance	_____	_____	_____

Subsequent Corner Restoration

Year surveyed 10/1984 By J.H. Parker, LS 9235
Location filed: Certificate of Location T144N R25W
Monument: Set 2.5" by 24" iron pipe w/ brass cap at the lost position, midway and on line between 1/4 S21 S28 Sec. corners. 1984 RLS 9235

Evidence of Subsequent Corner Restoration

Year of search 11/2017 By CCHD/SO
Location filed: #2017.017
Monument: Found USFS iron pipe with brass cap up 1.2', in good condition and the following. Steel Sign Post, East, 3.1' Steel Sign Post, South, 3.0'

Bearing Trees, Reference Objects

Species	<u>Oak</u>	<u>White Spruce</u>
Diameter	<u>10"</u>	<u>12"</u>
Bearing	<u>N 60° E</u>	<u>S 20° E</u>
Distance	<u>18.19'</u>	<u>12.09'</u>

Bearing Trees, Reference Objects

Species	<u>Burr Oak</u>	<u>Spruce</u>	<u>Spruce</u>
Diameter	<u>10"(1984)</u>	<u>14"(1984)</u>	<u>12"</u>
Bearing	<u>N 60° E</u>	<u>S 20° E</u>	<u>N 78° W</u>
Distance	<u>18.19'</u>	<u>12.09'</u>	<u>24.94'</u>

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed: _____
Monument: _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
Location filed: _____
Monument: _____

Species
Diameter
Bearing
Distance

Bearing Trees, Reference Objects

Bearing Trees, Reference Objects

Year surveyed
Location filed
Monument

By

Year of search
By

Subsequent Corner Restoration

Evidence of Subsequent Corner Restoration

Species
Diameter
Bearing
Distance

Bearing Trees
Balsam Poplar 8"
Ironwood 5"
NSW 54E
3475
3875

Species
Diameter
Bearing
Distance

Original Bearing Trees Found

Year surveyed
Original monument

Original Government Survey


Year of search
Monument found
Original Evidence Found

EXISTING SURVEYS

CASS COUNTY LAND CORNER RECORD

Index No. R 11

T 144 R 25 M 5TH Coordinates: X
Corner common to sections N 1/4 28
2128



R-11

Subsequent Corner Restoration

Evidence of Subsequent Corner Restoration Found

Year surveyed _____ By _____
Location filed _____
Monument _____

Year of search _____ By _____

Certificate - Jim Parker - 1985
Set lost - 2 1/2 x 60" 1/2 P. w/cap.
10" oak N60E 18.19'
12" W. Spruce 520E 12.09'
Doc # 281959

Remonumentation certificate prepared _____

By _____

Filed at _____

Date _____