

Species
Diameter
Bearing
Distance

Bearing Trees, Reference Objects

Year surveyed
Location filed
Monument

By

Year of search

By

Bearing Trees, Reference Objects

Subsequent Corner Restoration

Evidence of Subsequent Corner Restoration

Species
Diameter
Bearing
Distance

Bearing Trees

Aspen 5" 10' 187K5
Balsam 6" 10' 187K5
Aspen 8" 10' 187K5
Brch 8" 10' 187K5

Original Bearing Trees Found

Year of search

Original Evidence Found

Original Government Survey


EXISTING SURVEYS

Year surveyed 1876
Original monument: Post

Coordinates: X 22,832,627 Y 144 R 25 M 57H
T. NE 27 Corner common to sections 22,832,627

CASS COUNTY LAND CORNER RECORD

Index No. R17



Subsequent Corner Restoration

Evidence of Subsequent Corner Restoration Found

Year surveyed _____ By _____
Location filed _____
Monument _____

Year of search _____ By _____

Certificate - Jim Parker - 1985
set by double proportion 2 1/2" I.P. w/ cap.
4" w. Spruce N67E 84.11'
15" Aspen 528E 71.66'
12" Basswood S36W 27.10'
8" Aspen N25W 7.49'
Doc. # 281962

Remuneration certificate prepared _____

By _____

Filed at _____

Date _____