

Species
Diameter
Bearing
Distance

Bearing Trees, Reference Objects

Monument

Year surveyed
Location filed

By

Subsequent Corner Restoration

Species
Diameter
Bearing
Distance

Bearing Trees

Year surveyed 1876
Original monument post

Original Government Survey

EXISTING SURVEYS

T. 144 R. 25 M. 5TH Coordinates: X 23, 24, 25, 26
Corner common to sections 23, 24, 25, 26

CASS COUNTY LAND CORNER RECORD

Index No. R21

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____

Certificate - Jim Parker - 1985
Set obliterated from 1920 Corp's mta - set
3/8" x 8' long aluminum rod with stamped cap
Sign post 2.90' East
DOC. # 281964

Remonumentation certificate prepared _____ By _____
Filed at _____ Date _____

Bearing Trees, Reference Objects

Evidence of Subsequent Corner Restoration

Species
Diameter
Bearing
Distance

Original Bearing Trees Found

Year of search _____ By _____
Monument found _____

Original Evidence Found

O = Corner

