

Species
Diameter
Bearing
Distance

Bearing Trees, Reference Objects

Monument
Location filed
Year surveyed

By

Subsequent Corner Restoration

Species
Diameter
Bearing
Distance

Bearing Trees
No trees

Year surveyed *1876*
Original monument *lost*

Original Government Survey

EXISTING SURVEYS

Original Evidence Found
Year of search By
Monument found

Original Bearing Trees Found

Species
Diameter
Bearing
Distance

Evidence of Subsequent Corner Restoration


Year of search By

Bearing Trees, Reference Objects

Index No. *R23*

CASS COUNTY LAND CORNER RECORD

T 14 N 14 R 85 M 577 Coordinates: X *2425* Y
Corner common to sections *2425*



Evidence of Subsequent Corner Restoration Found

Year of search By

Subsequent Corner Restoration

Year surveyed By
Location filed
Monument

Remonumentation certificate prepared By
Filed at Date