

Species _____
Diameter _____
Bearing _____
Distance _____

Bearing Trees, Reference Objects

Year surveyed _____
Location filed _____
Monument _____

Subsequent Corner Restoration

Species _____
Diameter _____
Bearing _____
Distance _____

Ash 6" 502E 28 YRS
Ash 8" 502E 13 YRS
Ash 5" 567W 14 YRS
LYNN 8" 14 YRS

Year surveyed 1876
Original monument Post
Original Government Survey

EXISTING SURVEYS

T. 144 R. 25 M. 5TH Coordinates: X NE 30 Corner common to sections 19, 20, 29, 30

CASS COUNTY LAND CORNER RECORD

Index No. 85

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____

Certificate - Jim Parker - 1985
Set by double proportion 2" 2" i.p. w/ brass cap
6" Ash N73°E 43.49'
8" Ash S40°E 30.61'
6" Ash S45°W 4.90'
5" Balsam N29°W 51.14'
Doc. # 281956


Bearing Trees, Reference Objects

Evidence of Subsequent Corner Restoration

Species _____
Diameter _____
Bearing _____
Distance _____

Year of search _____
Original Evidence Found _____
Monument found _____
Original Bearing Trees Found _____

O = Corner



R-5

Remonumentation certificate prepared _____ By _____
Filed at _____ Date _____