


T. 144 R. 26 M. 5th Coordinates: X \_\_\_\_\_ Y \_\_\_\_\_

E 1/4 25 Corner common to sections 25 and 30/144/25



EXISTING SURVEYS

Original Government Survey

Year surveyed 1873  
Original monument Post

Original Evidence Found

Year of search 1912 by Todd  
Monument found \_\_\_\_\_  
Survey Rec #211, Bk A, pg 517

Bearing Trees

Species	<u>Spruce</u>	<u>Cedar</u>
Diameter	<u>5"</u>	<u>12"</u>
Bearing	<u>S 59° E</u>	<u>S 68° W</u>
Distance	<u>8 links</u>	<u>13 links</u>

Original Bearing Trees Found

Species	<u>Cedar</u>	_____
Diameter	<u>12"</u>	_____
Bearing	<u>S 68° W</u>	_____
Distance	<u>13 links</u>	_____

Subsequent Corner Restoration

Year surveyed 2/1903 By O.C. Gilbert  
Location filed: Road Calendar A, page 44  
Monument: Zuzu-Bear River Road, indicates corner position in road. This information also in Road Calendar B, page 30

Evidence of Subsequent Corner Restoration

Year of search 3/1912 By H.S. Todd  
Location filed: Survey Record #211, Book A, page 517 and Curo  
Monument: Set stake Curo Book 98, page 80, corner and bearing trees gone.

Bearing Trees, Reference Objects

Species	_____	_____
Diameter	_____	_____
Bearing	_____	_____
Distance	_____	_____

Bearing Trees, Reference Objects

Species	<u>Cedar</u>	<u>Ash</u>
Diameter	<u>12"</u>	<u>12"</u>
Bearing	<u>N 52°30' E</u>	<u>S 70°26' E</u>
Distance	<u>42.25'</u>	<u>54.20'</u>

Subsequent Corner Restoration

Year surveyed 1/1914 By J.W. Curo, LS 1428  
Location filed: Survey Record #322, Book B, page 414 and Curo  
Monument: Nail on old stake Curo Book 98, page 112, red flag at 1/4 corner and notes new bearing trees by Todd.

Evidence of Subsequent Corner Restoration Found

Year of search 8/2011 By CCHD/SO  
Location filed: #2011.015  
Monument: Set Mag nail from witnesses after construction, 0.5' east of new center line CSAH #3.

12/1983, J.R. Worcester, CCHD S.P. 11-603-05 Corner assumed at Station 155+91.1

7/2019, CCHD/SO #2011.015 Found Conc. nail, 0.5', E. of centerline CSAH #3. 1984 and 2011 witnesses are good.

9/1984, J.H. Parker, LS 9235 Certificate of Location Set 5/8"x 36" aluminum rod monument with cap, at obliterated position at intersection of fence line and centerline CSAH #3, down 0.3' and witnessed. 8" Birch, N 40° W, 131.01' 6" Ash, N 67° E, 76.50'


7/2019, T.L. Freeman, LS 21367 Certificate of Location, A000651784 Filed on the above information.

7/2011, CCHD/SO #2011.015 Found P.K. set from 1984 witnesses, on center line Co. Rd. #3 and add the following: P. Pole, N 21° W, 119.56' NW Cor Elec. Cab., S 48° W, 73.67'

Index No. T 25

CASS COUNTY LAND CORNER RECORD

T. 144 R. 26 M. 5TH Coordinates: X \_\_\_\_\_ Y \_\_\_\_\_  
E 1/4 25 Corner common to sections 25 AND 30-144-25



EXISTING SURVEYS

Original Government Survey  
Year surveyed 1873  
Original monument Post

Original Evidence Found  
Year of search \_\_\_\_\_ By \_\_\_\_\_  
Monument found \_\_\_\_\_

Bearing Trees  
Species Spruce Cedar  
Diameter 5" 12"  
Bearing S59E S68W  
Distance 8 LKS 13 LKS

Original Bearing Trees Found  
Species \_\_\_\_\_  
Diameter \_\_\_\_\_  
Bearing \_\_\_\_\_  
Distance \_\_\_\_\_

Subsequent Corner Restoration  
Year surveyed 1912 By HARRY S. TODD  
Location filed COUNTY SURVEY RECORD BOOK "A" P516-518  
Monument FIND OLD GOVT BIT: 12" CEDAR S68W 13 LKS, SET STAKE

Evidence of Subsequent Corner Restoration  
Year of search \_\_\_\_\_ By \_\_\_\_\_

Bearing Trees, Reference Objects  
Species CEGAR ASH  
Diameter 12" 12"  
Bearing N52-30E S70-26E  
Distance 42.25' 54.20'

Bearing Trees, Reference Objects  
\_\_\_\_\_

7-25

Subsequent Corner Restoration  
Year surveyed \_\_\_\_\_ By \_\_\_\_\_  
Location filed \_\_\_\_\_  
Monument \_\_\_\_\_

Evidence of Subsequent Corner Restoration Found  
Year of search \_\_\_\_\_ By \_\_\_\_\_  
Cert. Eicate - Jim Parker - 1985  
Set obliterated 5/8 x 3/8" aluminum rod w/ cap  
6" Ash N67°E 76.50'  
8" Birch N48°W 131.01'  
Doc. # 281965

Remonumentation certificate prepared \_\_\_\_\_ By \_\_\_\_\_  
Filed at \_\_\_\_\_ Date \_\_\_\_\_