


T. 144 R. 25 M. 5th Coordinates: X _____ Y _____

NE 32 Corner common to sections 28,29,32,33



EXISTING SURVEYS

Original Government Survey

Year surveyed 1876
Original monument Post

Original Evidence Found

Year of search _____ by _____
Monument found _____

Bearing Trees

Species	<u>Tam.</u>	<u>W. Pine</u>	<u>Cedar</u>	<u>Willow</u>
Diameter	<u>6"</u>	<u>7"</u>	<u>5"</u>	<u>5"</u>
Bearing	<u>N 40° E</u>	<u>N 44° W</u>	<u>S 47° W</u>	<u>S 87° E</u>
Distance	<u>6 links</u>	<u>29 links</u>	<u>26 links</u>	<u>12 links</u>

Original Bearing Trees Found

Species	_____	_____	_____	_____
Diameter	_____	_____	_____	_____
Bearing	_____	_____	_____	_____
Distance	_____	_____	_____	_____

Subsequent Corner Restoration

Year surveyed 12/1983 By J.R. Worcester, CCHD
Location filed: S.P. 11-603-07
Monument: Assumed at Sta. 284+84.1

Evidence of Subsequent Corner Restoration

Year of search 9/1984 By J.H. Parker, LS 9235
Location filed: Certificate of Location
Monument: Found 1/2" x 13" iron pipe on center line Set 5/8"x 36" aluminum rod monument with cap, down 0.5' on center line of CSAH #3 and center line of Township Road to North.

Bearing Trees, Reference Objects

Species	<u>Birch</u>	<u>Pop</u>	<u>Pop</u>	_____
Diameter	<u>6"</u>	<u>12"</u>	<u>5"</u>	_____
Bearing	<u>NW</u>	<u>NE</u>	<u>SSE</u>	_____
Distance	<u>109.1'</u>	<u>70.5'</u>	<u>123.4'</u>	_____

Bearing Trees, Reference Objects

Species	<u>Spruce</u>	<u>W. Oak</u>	<u>Aspen</u>	<u>Aspen</u>
Diameter	<u>18"</u>	<u>8"</u>	<u>7"</u>	<u>8"</u>
Bearing	<u>N 44° W</u>	<u>N 73° E</u>	<u>S 42° E</u>	<u>S 59° W</u>
Distance	<u>81.48'</u>	<u>170.81'</u>	<u>116.52'</u>	<u>176.22'</u>

Subsequent Corner Restoration

Year surveyed 8/2011 By CCHD/SO
Location filed: #2011.015
Monument: Set Mag nail from 1984 witness and recovered 1/4 corners east and west, on new center line CSAH #3 and add the following:
10" Spruce, N 50° W, 137.70'
12" Maple, N 44° E, 126.47'
NW Elec. cab., S 24° W, 64.02'

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
Location filed: _____
Monument: _____

10/2017, CCHD/SO #2017.017
Found 2011 concrete nail, in good condition on centerlines of CSAH #3 and 80th Avenue, and 1984 and 2011 witnesses in good condition.

7/2019, CCHD/SO #2017.017
Replaced conc. nail with Alum. Co. mon., down 0.05', on centerline of CSAH #3 and 80th Avenue. witnesses good.

7/2019, T.L. Freeman, LS 21367
Certificate of Location, A000651789
Filed on the above information.

Species
Diameter
Bearing
Distance

Bearing Trees, Reference Objects

Monument

Location filed

Year surveyed By

Subsequent Corner Restoration

Species
Diameter
Bearing
Distance

Species	6 LKS	39 LKS	26 LKS	12 LKS
Bearing	N40E	N44W	547W	S87E
Diameter	6"	7"	5"	3"
Species	Tan	W. Pine	Cedar	Willow

Year surveyed 1876
Original monument lost

Original Government Survey

EXISTING SURVEYS

Coordinates: X 144 R. 25 M. 571 NE 32
Corner common to sections 28, 29, 32, 33

CASS COUNTY LAND CORNER RECORD

Index No. V9

Subsequent Corner Restoration

Year surveyed By

Location filed


Monument

Evidence of Subsequent Corner Restoration Found

Year of search By

Certificate - Jim Parkey - 1985
 Fnd 1/2" I.P. - set 3/8" X 36" aluminum rod
 w/stamped cap
 8" W. oak N73E 170.81'
 7" Aspen 542E 116.52'
 8" Aspen 559W 176.22'
 18" Spruce N44W 81.48'
 Doc # 281974

6-1



Remonumentation certificate prepared
Filed at

By
Date